


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-227	Smoke	8/11/2009	ADS/TM	S21MM_018MH	Dry	Yes	662.32



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-227	Smoke	8/11/2009	ADS/TM	S21MM_018MH	Dry	Yes	662.32

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S21MM_018G1	S21MM_018MH	S21MM_014MH	45.2061	8
S21MM_009G1	S21MM_009MH	S21MM_014MH	101.104	8
S23MM_013G1	S23MM_013MH	S21MM_018MH	312.646	8
S21MM_103G1	S21MM_103MH	S21MM_009MH	203.366	8

Observations & Photos

Obs_ID S1028-227-OB01

Address 1547 Clifton Ave


Status Private

Source Cleanout

Location Yard - back

Nearest MH S21MM_009MH

Comments Smoke from cleanout in back yard. 1547 Clifton Ave.



Picture \S1028-227-OB01-P01.jpg

Comments Back of house, 1547 Clifton Ave.

Obs_ID S1028-227-OB02

Address 2235 Fulton Ave


Status Private

Source Service Lateral

Location Sidewalk

Nearest MH S21MM_018MH

Comments Smoke from service lateral underneath sidewalk. 2235 Fulton Ave.



Picture \S1028-227-OB02-P01.jpg

Comments Side of school building, 2235 Fulton Ave.